

# Grants Pass High School

Grants Pass SD 7

Jose\_sch06A

Building Type School	County Josephine	
Street 830 Ne 9th St		
City Grants Pass	State OR	Zip 97526
Latitude 42.44447	Longitude 123.31797	
Tracking Code New Building	Inspection Date 9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Grants Pass High School

## Final RVS Score

Final Type	Final Score
<input type="text"/>	<input type="text"/>

## FEMA-154 Collapse Potential

Low (<1%)

No  
Planview  
Available



OregonGeology

# Grants Pass High School

Jose\_sch06A

Enrollment 1994	Year Built (Field Verified) 1997	Year Built (Alt. Source) 1997	Est. Decade Built
Total Area (square ft) 277774	Number of Stories	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	