

Fleming Middle School

Three Rivers/Josephine County SD

Jose_sch08A

Building Type	County	
School	Josephine	
Street		
6001 Monument Dr		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.50679	123.37427	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fleming Middle School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Fleming Middle School

Jose_sch08A

Enrollment 485	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1960
Total Area (square ft) 76245	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Fleming Middle School

Three Rivers/Josephine County SD

Jose_sch08B

Building Type	County	
School	Josephine	
Street		
6001 Monument Dr		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.50722	123.37417	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Fleming Middle School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Fleming Middle School

Jose_sch08B

Enrollment 485	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 76245	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
			
NE Plan Irregularity Primary		S Falling Hazard covered walkway	E Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Fleming Middle School

Three Rivers/Josephine County SD

Jose_sch08C

Building Type	County	
School	Josephine	
Street		
6001 Monument Dr		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.50728	123.37359	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fleming Middle School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Fleming Middle School

Jose_sch08C

Enrollment 485	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1960
Total Area (square ft) 76245	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
 S Falling Hazard			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Fleming Middle School

Three Rivers/Josephine County SD

Jose_sch08D

Building Type	County	
School	Josephine	
Street		
6001 Monument Dr		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.50651	123.37366	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fleming Middle School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Fleming Middle School

Jose_sch08D

Enrollment 485	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1960
Total Area (square ft) 76245	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
 SW Falling Hazard			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Fleming Middle School

Three Rivers/Josephine County SD

Jose_sch08E

Building Type	County	
School	Josephine	
Street		
6001 Monument Dr		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.50661	123.37404	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fleming Middle School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Fleming Middle School

Jose_sch08E

Enrollment 485	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1960
Total Area (square ft) 76245	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
			
N Falling Hazard			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Fleming Middle School

Three Rivers/Josephine County SD

Jose_sch08F

Building Type	County	
School	Josephine	
Street		
6001 Monument Dr		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.50649	123.37448	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fleming Middle School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Fleming Middle School

Jose_sch08F

Enrollment 485	Year Built (Field Verified) 1962	Year Built (Alt. Source) 1962	Est. Decade Built 1960
Total Area (square ft) 76245	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	