

# Fruitdale Elementary School

Three Rivers/Josephine County SD

Jose\_sch09A

Building Type	County	
School	Josephine	
Street		
1560 Hamilton Ln		
City	State	Zip
Grants Pass	OR	97527
Latitude	Longitude	
42.42049	123.31162	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fruitdale Elementary School

## Final RVS Score

Final Type      Final Score

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Fruitdale Elementary School

Jose\_sch09A

Enrollment 300	Year Built (Field Verified) 2003	Year Built (Alt. Source) 2003	Est. Decade Built
Total Area (square ft) 31109	Number of Stories	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S	General Site	S	General Site
			
S	General Site		
			
S	General Site	S	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries