

Ft Vannoy Elementary School

Three Rivers/Josephine County SD

Jose_sch10A

Building Type		County	
School		Josephine	
Street			
5250 Upper River Rd.			
City	State	Zip	
Grants Pass	OR	97526	
Latitude		Longitude	
42.44718		123.41408	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

Ft Vannoy Elementary School

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
308		1967	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
40100	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Ft Vannoy Elementary School

Jose_sch10B

Three Rivers/Josephine County SD

Building Type		County	
School		Josephine	
Street			
5250 Upper River Rd.			
City	State	Zip	
Grants Pass	OR	97526	
Latitude		Longitude	
42.44762		123.41461	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ft Vannoy Elementary School

Final RVS Score

Final Type

Final Score

RM1

1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
308		1967	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
40100	1	No	No

Plan Irregularities	Vertical Irregularities
Out of Plane Lateral-Force-Resistance Elements	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None




NE General Site

Ft Vannoy Elementary School

Three Rivers/Josephine County SD

Jose_sch10C

Building Type		County	
School		Josephine	
Street			
5250 Upper River Rd.			
City	State	Zip	
Grants Pass	OR	97526	
Latitude		Longitude	
42.44728		123.41508	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ft Vannoy Elementary School

Final RVS Score

Final Type

Final Score

RM1

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
308		1967	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
40100	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Vertical Irregularity Primary

E Primary Structural Type

