

Jerome Prairie Elementary School

Three Rivers/Josephine County SD

Jose_sch11A

Building Type	County	
School	Josephine	
Street		
2555 Walnut Ave.		
City	State	Zip
Grants Pass	OR	97527
Latitude	Longitude	
42.40703	123.43209	
Tracking Code	Inspection Date	
RVS in 2006	7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	-1	0	0	0	0	2.3
Secondary	RM1	2.8	0	-0.5	-1	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Jerome Prairie Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jerome Prairie Elementary School

Jose_sch11A

Enrollment 256	Year Built (Field Verified) 1938	Year Built (Alt. Source) 1938	Est. Decade Built 1930
Total Area (square ft) 30838	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
NE Plan Irregularity Primary		NE Plan Irregularity Secondary Secondary structural type can also be seen.	
		S Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jerome Prairie Elementary School

Three Rivers/Josephine County SD

Jose_sch11B

Building Type	County	
School	Josephine	
Street		
2555 Walnut Ave.		
City	State	Zip
Grants Pass	OR	97527
Latitude	Longitude	
42.40673	123.43242	
Tracking Code	Inspection Date	
RVS in 2006	7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jerome Prairie Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jerome Prairie Elementary School

Jose_sch11B

Enrollment 256	Year Built (Field Verified) 1938	Year Built (Alt. Source) 1938	Est. Decade Built 1950
Total Area (square ft) 30838	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Jerome Prairie Elementary School

Three Rivers/Josephine County SD

Jose_sch11C

Building Type	County	
School	Josephine	
Street		
2555 Walnut Ave.		
City	State	Zip
Grants Pass	OR	97527
Latitude	Longitude	
42.40675	123.43202	
Tracking Code	Inspection Date	
RVS in 2006	7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jerome Prairie Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jerome Prairie Elementary School

Jose_sch11C

Enrollment 256	Year Built (Field Verified) 1938	Year Built (Alt. Source) 1938	Est. Decade Built 1950
Total Area (square ft) 30838	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Jerome Prairie Elementary School

Three Rivers/Josephine County SD

Jose_sch11D

Building Type	County	
School	Josephine	
Street		
2555 Walnut Ave.		
City	State	Zip
Grants Pass	OR	97527
Latitude	Longitude	
42.40635	123.43219	
Tracking Code	Inspection Date	
RVS in 2006	7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	-1	0	0	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jerome Prairie Elementary School

Final RVS Score

Final Type	Final Score
W2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Jerome Prairie Elementary School

Jose_sch11D

Enrollment 256	Year Built (Field Verified) 1938	Year Built (Alt. Source) 1930	Est. Decade Built 1930
Total Area (square ft) 30838	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	



W Plan Irregularity Primary



W Falling Hazard



E General Site
New roof.



S Vertical Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries