


Lincoln Savage Middle School

Jose_sch12A

Three Rivers/Josephine County SD

Building Type	County	
School	Josephine	
Street		
8551 New Hope Rd.		
City	State	Zip
Grants Pass	OR	97527
Latitude		Longitude
42.34813		123.33495
Tracking Code		Inspection Date
RVS in 2006		7/28/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Savage Middle School

Final RVS Score

Final Type

Final Score

RM1

2.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
502	1962	1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
71583	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW Primary Structural Type



SE General Site

Lincoln Savage Middle School

Jose_sch12B

Three Rivers/Josephine County SD

Building Type		County	
School		Josephine	
Street			
8551 New Hope Rd.			
City		State	Zip
Grants Pass		OR	97527
Latitude		Longitude	
42.34829		123.33469	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Savage Middle School

Final RVS Score

Final Type

Final Score

RM1

2.2

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
502		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
71583	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Lincoln Savage Middle School

Three Rivers/Josephine County SD

Jose_sch12C

Building Type		County	
School		Josephine	
Street			
8551 New Hope Rd.			
City	State	Zip	
Grants Pass	OR	97527	
Latitude	Longitude		
42.34828	123.33544		
Tracking Code	Inspection Date		
RVS in 2006	7/28/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Savage Middle School

Final RVS Score

Final Type

Final Score

RM1

1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
502		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
71583	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Plan Irregularity Primary



Lincoln Savage Middle School

Three Rivers/Josephine County SD

Jose_sch12D

Building Type		County	
School		Josephine	
Street			
8551 New Hope Rd.			
City		State	Zip
Grants Pass		OR	97527
Latitude		Longitude	
42.34862		123.33494	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary	W2	3.8	0	-0.5	0	0	0	-0.8	0	2.5
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Savage Middle School

Final RVS Score

Final Type

Final Score

RM1

1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
502		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
71583	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Vertical Irregularity Primary



NE Secondary Structural Type



Lincoln Savage Middle School

Jose_sch12E

Three Rivers/Josephine County SD

Building Type		County	
School		Josephine	
Street			
8551 New Hope Rd.			
City	State	Zip	
Grants Pass	OR	97527	
Latitude	Longitude		
42.34875	123.33545		
Tracking Code	Inspection Date		
RVS in 2006	7/28/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Savage Middle School

Final RVS Score

Final Type

Final Score

RM1

2.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
502		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
71583	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

Lincoln Savage Middle School

Jose_sch12F

Three Rivers/Josephine County SD

Building Type		County	
School		Josephine	
Street			
8551 New Hope Rd.			
City	State	Zip	
Grants Pass	OR	97527	
Latitude		Longitude	
42.34868		123.33439	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Savage Middle School

Final RVS Score

Final Type

Final Score

RM1

2.2

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
502		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
50952	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Lincoln Savage Middle School

Jose_sch12G

Three Rivers/Josephine County SD

Building Type		County	
School		Josephine	
Street			
8551 New Hope Rd.			
City		State	Zip
Grants Pass		OR	97527
Latitude		Longitude	
42.34828		123.33429	
Tracking Code		Inspection Date	
RVS in 2006		7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Savage Middle School

Final RVS Score

Final Type

Final Score

RM1

2.2

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
502		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
71583	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

