

Lorna Byrne Middle School

Three Rivers/Josephine County SD

Jose_sch13A

Building Type	County	
School	Josephine	
Street		
101 S Junction Ave		
City	State	Zip
Cave Junction	OR	97523
Latitude	Longitude	
42.16688	123.64328	
Tracking Code	Inspection Date	
RVS in 2006	7/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lorna Byrne Middle School

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lorna Byrne Middle School

Jose_sch13A

Enrollment 338	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 57418	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change Building On Hill or Sloped Site None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
			
E Plan Irregularity Primary	SW Vertical Irregularity Primary	NW Vertical Irregularity Secondary	
			
W Falling Hazard	N Other New part of school built in 2003 - not screened.	N Other New part of school built on 2003.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries