

# Manzanita Elementary School

Three Rivers/Josephine County SD

Jose\_sch14A

Building Type	County	
School	Josephine	
Street		
310 San Francisco St.		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.5066	123.37201	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Manzanita Elementary School

## Final RVS Score

Final Type	Final Score
RM1	2.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Manzanita Elementary School

Jose\_sch14A

Enrollment 385	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 48649	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 <p>MANZANITA ELEMENTARY SCHOOL JOSEPHINE COUNTY SCHOOL DISTRICT BOARD OF EDUCATION ROBERT J. RUST CHAIRMAN JOAN MUELEMANN VICE CHAIRMAN WILLIAM JENSEN DONALD ROSENBERG EDWARD McALVAGE TOM W. CALKINS SUPERINTENDENT NETTIE E. SCHWEINFURT CLERK ARCHITECT: EDDIE N. PATTERSON, AIA CONTRACTOR: W. H. AUSLAND 1967</p>			
S Field Verified Year Built			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Manzanita Elementary School

Three Rivers/Josephine County SD

Jose\_sch14B

Building Type	County	
School	Josephine	
Street		
310 San Francisco St.		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.50661	123.37145	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Manzanita Elementary School

## Final RVS Score

Final Type	Final Score
RM1	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Manzanita Elementary School

Jose\_sch14B

Enrollment 385	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 48649	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S Vertical Irregularity Primary		SE Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Manzanita Elementary School

Three Rivers/Josephine County SD

Jose\_sch14C

Building Type	County	
School	Josephine	
Street		
310 San Francisco St.		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.50659	123.37233	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Manzanita Elementary School

## Final RVS Score

Final Type	Final Score
RM1	1.9

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Manzanita Elementary School

Jose\_sch14C

Enrollment 385	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 48649	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Non-Parallel System None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S General Site Building 2	W General Site Building 3	W Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Manzanita Elementary School

Three Rivers/Josephine County SD

Jose\_sch14D

Building Type	County	
School	Josephine	
Street		
310 San Francisco St.		
City	State	Zip
Grants Pass	OR	97526
Latitude	Longitude	
42.5062	123.37249	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	2.4	0	0	0	6.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Manzanita Elementary School

## Final RVS Score

Final Type	Final Score
W1	6.8

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Manzanita Elementary School

Jose\_sch14D

Enrollment 385	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1990
Total Area (square ft) 48649	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	