

Highland Elementary School

Grants Pass SD 7

Jose_sch21A

Building Type School	County Josephine	
Street 1845 NW Highland Ave.		
City Grants Pass	State OR	Zip 97526
Latitude 42.46052	Longitude 123.33176	
Tracking Code RVS in 2006	Inspection Date 7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	0	0	0	0	0	0	1.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Highland Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.8

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Highland Elementary School

Jose_sch21A

Enrollment 409	Year Built (Field Verified) 1957	Year Built (Alt. Source) 1957	Est. Decade Built 1940
Total Area (square ft) 63077	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W	Vertical Irregularity Primary	W	Plan Irregularity Primary
			
		E	General Site