

Klamath - Building 3

Klam_coc01A

Klamath CC

| | | | |
|-------------------|-----------------|---------|--|
| Building Type | | County | |
| Community_College | | Klamath | |
| Street | | | |
| 7390 S 6th Street | | | |
| City | State | Zip | |
| Klamath Falls | OR | 97603 | |
| Latitude | Longitude | | |
| 42.19514 | 121.69873 | | |
| Tracking Code | Inspection Date | | |
| New Building | 3/1/2007 | | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | S3 | 3.2 | | | | | -0.6 | | | |
| Secondary | | | | | | | | | | |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Klamath - Building 3

Final RVS Score

Final Type


Final Score

S3

2.6

FEMA-154 Collapse Potential

Low (<1%)



| | | | |
|------------------------|-----------------------------|--------------------------|----------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| <input type="text"/> | <input type="text"/> | 1999 | <input type="text"/> |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 16000 | 1 | No | No |

| | |
|----------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |

| | |
|----------------------|----------------------|
| Falling Hazards | Poor Conditions |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |
| <input type="text"/> | <input type="text"/> |



S General Site



S General Site

