

# Klamath County Fire District 1

Klam\_fir07A

Klamath Co Fire Dist #1

Building Type Fire - RFPD	County Klamath	
Street 2342 Gettle St.		
City Klamath Falls	State OR	Zip 97603
Latitude 42.20586	Longitude 121.73296	
Tracking Code RVS in 2006	Inspection Date 7/21/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	0	0	0	-0.6	0	-0.3
Secondary	RM1	2.8	-1	-0.5	-1	0	0	-0.6	0	-0.3
Tertiary	S3	3.2	0	-0.5	0	0	0	-0.6	0	2.1

Klamath County Fire District 1

## Final RVS Score

Final Type	Final Score
URM	-0.3

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Klamath County Fire District 1

Klam\_fir07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1948	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
13500	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Vertical Irregularity Primary	E	Plan Irregularity Primary
			
E	Primary Structural Type		
			
SE	Elevation View	SW	Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries