

Harriman RFPD

Harriman RFPD

Klam_fir11A

Building Type Fire - RFPD	County Klamath	
Street 25600 Rocy Point Rd.		
City Klamath Falls	State OR	Zip 97601
Latitude 42.45956	Longitude 122.10627	
Tracking Code RVS in 2006	Inspection Date 7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	0	-0.6	0	2.1
Secondary	W1	4.4	-2.5	-0.5	0	2.4	0	0	0	3.8
Tertiary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7

Harriman RFPD

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Elevation View	S	Vertical Irregularity Primary

