

# Bonanza RFPD

Klam\_fir12A

## Bonanza RFPD

Building Type Fire - RFPD	County Klamath	
Street 2849 Market St.		
City Bonanza	State OR	Zip 97623
Latitude 42.19954	Longitude 121.40031	
Tracking Code RVS in 2006	Inspection Date 7/21/2006	



Seismicity Zone: Moderate

### FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary	S3	3.8	0	-0.5	0	0	0	-1	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Bonanza RFPD

### Final RVS Score

Final Type	Final Score
RM1	1.9

### FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
14000	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Building Shape		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	General Site	E	Primary Structural Type

