

Bly RFPD

Bly RFPD

Klam_fir13A

Building Type		County	
Fire - RFPD		Klamath	
Street			
60800 Highway 140E			
City	State	Zip	
Bly	OR	97622	
Latitude		Longitude	
42.40658		121.04901	
Tracking Code		Inspection Date	
RVS in 2006		7/21/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	0	0	0	3.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Bly RFPD

Final RVS Score

Final Type

Final Score

S3

3.3

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW General Site



Bly RFPD

Bly RFPD

Klam_fir13B

Building Type	County		
Fire - RFPD	Klamath		
Street			
60800 Highway 140E			
City	State	Zip	
Bly	OR	97622	
Latitude	Longitude		
42.40685	121.04897		
Tracking Code	Inspection Date		
RVS in 2006	7/21/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	0	0	0	0	5.2
Secondary	S3	3.8	0	0	0	0	0	0	0	3.8
Tertiary	RM1	3.6	0	0	0	0	0	0	0	3.6

Bly RFPD

Final RVS Score

Final Type

Final Score

RM1

3.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None