

Klamath County Fire District 4

Klamath County Fire District 4

Klam_fir18A

Building Type Fire - RFPD	County Klamath	
Street 4042 Balsam Dr		
City Klamath Falls	State OR	Zip 97601
Latitude 42.19209	Longitude 121.80799	
Tracking Code RVS in 2006	Inspection Date 7/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	0	0	0	0	0	0	1.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Klamath County Fire District 4

Final RVS Score

Final Type	Final Score
RM1	1.8

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Klamath County Fire District 4

Klam_fir18A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1955	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
12305	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE	Vertical Irregularity Primary	NE	Plan Irregularity Primary
			
		S	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries