

Klamath County

Building Type		County	
Police - County		Klamath	
Street			
3300 Vandenberg Rd			
City	State	Zip	
Klamath Falls	OR	97603	
Latitude		Longitude	
42.22262		121.7492	
Tracking Code		Inspection Date	
RVS in 2006		7/21/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	2.4	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Klamath County Sheriff's Office

Final RVS Score

Final Type

Final Score

W1

3.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S General Site



S Primary Structural Type



NW Plan Irregularity Primary



NW Vertical Irregularity Primary

