


Bonanza Elementary School

Klamath County SD

Klam_sch04A

Building Type	County	
School	Klamath	
Street		
31610 Mission St		
City	State	Zip
Bonanza	OR	97623
Latitude		Longitude
42.20025		121.40623
Tracking Code		Inspection Date
Structural Engineering Report		9/15/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	-0.4	0	0	0.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Bonanza Elementary School

Final RVS Score

Final Type

Final Score

URM

0.6

FEMA-154 Collapse Potential

High (>10%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
202		1944	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions