

# Chiloquin Elementary School

Klamath County SD

Klam\_sch05A

Building Type	County
School	Klamath
Street	
600 Second St	
City	State Zip
Chiloquin	OR 97624
Latitude	Longitude
42.57034	121.86492
Tracking Code	Inspection Date
Structural Engineering Report	9/15/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Chiloquin Elementary School

### Final RVS Score

Final Type	Final Score
RM1	-0.1

### FEMA-154 Collapse Potential

Very High (100%)

No  
Planview  
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Chiloquin Elementary School

Klam\_sch05A

Enrollment 256	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built
Total Area (square ft) 28266	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	