

Ferguson Elementary School

Klamath County SD

Klam_sch07A

| | | |
|--|------------------------------|--------------|
| Building Type School | County Klamath | |
| Street 2901 Homedale Rd | | |
| City Klamath Falls | State OR | Zip 97603 |
| Latitude 42.20024 | Longitude 121.72095 | |
| Tracking Code Structural Engineering Report | Inspection Date 9/15/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | 0 | 0 | 0 | -0.8 | 0 | 0.5 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Ferguson Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 0.5 |

FEMA-154 Collapse Potential

High (>10%)

No
Planview
Available



OregonGeology

Ferguson Elementary School

Klam_sch07A

| | | | |
|---------------------------------|-------------------------------------|----------------------------------|--------------------------|
| Enrollment 531 | Year Built (Field Verified) 1954 | Year Built (Alt. Source) 1954 | Est. Decade Built |
| Total Area (square ft) 39575 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities | | Vertical Irregularities | |
| | | | |
| | | | |
| | | | |
| Falling Hazards | | Poor Conditions | |
| | | | |
| | | | |
| | | | |