

Henley Middle School

Klamath County SD

Klam_sch13A

Building Type		County	
School		Klamath	
Street			
7925 Hwy 39			
City	State	Zip	
Klamath Falls	OR	97603	
Latitude		Longitude	
42.15354		121.69748	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Henley Middle School

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
468		1949	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
54525	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions