

Building Type	County
School	Klamath
Street	
8245 Hwy 39	
City	State Zip
Klamath Falls	OR 97603
Latitude	Longitude
42.15097	121.69389
Tracking Code	Inspection Date
Structural Engineering Report 9/15/2006	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0



Henley High School

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)

No
Planview
Available



Oregon Geology

Henley High School

Klam_sch15A

Enrollment 657	Year Built (Field Verified) 1964	Year Built (Alt. Source) 1964	Est. Decade Built
Total Area (square ft) 121200	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries