

Lost River High School

Klamath County SD

Klam_sch16A

Building Type		County	
School		Klamath	
Street			
23330 Hwy 50			
City	State	Zip	
Merrill	OR	97633	
Latitude		Longitude	
42.0158		121.50389	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lost River High School

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
287		1970	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
66650	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions