

Gilchrist Elementary School

Klamath County SD

Klam_sch25A

Building Type	County	
School	Klamath	
Street		
201 Mountain View Dr		
City	State	Zip
Gilchrist	OR	97737
Latitude	Longitude	
43.47811	121.6844	
Tracking Code	Inspection Date	
Structural Engineering Report		
9/15/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	-0.2	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Gilchrist Elementary School

Final RVS Score

Final Type	Final Score
W2	0.3

FEMA-154 Collapse Potential

High (>10%)

No
Planview
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Gilchrist Elementary School

Klam_sch25A

Enrollment 129	Year Built (Field Verified) 1938	Year Built (Alt. Source) 1938	Est. Decade Built
Total Area (square ft) 23720	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S General Site	S General Site	S General Site	
			
S General Site	S General Site	S General Site	
			
S General Site	S General Site	S General Site	
			
S General Site	S General Site	S General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Gilchrist Elementary School

Klam_sch25A



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



S General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries