

# Lakeview Police Dept

City of Lakeview

Lake\_pol03A

|               |       |                 |  |
|---------------|-------|-----------------|--|
| Building Type |       | County          |  |
| Fire - City   |       | Lake            |  |
| Street        |       |                 |  |
| 245 N F St    |       |                 |  |
| City          | State | Zip             |  |
| Lakeview      | OR    | 97630           |  |
| Latitude      |       | Longitude       |  |
| 42.19119      |       | 120.34626       |  |
| Tracking Code |       | Inspection Date |  |
| RVS in 2006   |       | 6/27/2006       |  |



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W1   | 5.2         | -3.5       | -0.5       | 0        | 1.6        | 0      | -0.6   | 0      | 2.2       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Lakeview Police Dept

## Final RVS Score

Final Type


Final Score

W1

2.2

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

|                        |                                   |                                   |                                   |
|------------------------|-----------------------------------|-----------------------------------|-----------------------------------|
| Enrollment             | Year Built (Field Verified)       | Year Built (Alt. Source)          | Est. Decade Built                 |
| <input type="text"/>   | <input type="text" value="1984"/> | <input type="text" value="1984"/> | <input type="text" value="1980"/> |
| Total Area (square ft) | Number of Stories                 | Basement                          | Pounding Potential                |
| <input type="text"/>   | <input type="text" value="1"/>    | <input type="text" value="No"/>   | <input type="text" value="Yes"/>  |

|                                                     |                                                                   |
|-----------------------------------------------------|-------------------------------------------------------------------|
| Plan Irregularities                                 | Vertical Irregularities                                           |
| Reentrant Corners: L shaped (Adjacent Build/Entity) | Steps in Elevation View: Single Change (Adjacent Building/Entity) |
| <input type="text" value="None"/>                   | <input type="text" value="None"/>                                 |
| <input type="text" value="None"/>                   | <input type="text" value="None"/>                                 |

|                                   |                                   |
|-----------------------------------|-----------------------------------|
| Falling Hazards                   | Poor Conditions                   |
| <input type="text" value="None"/> | <input type="text" value="None"/> |
| <input type="text" value="None"/> | <input type="text" value="None"/> |
| <input type="text" value="None"/> | <input type="text" value="None"/> |



E Pounding Potential



S Primary Structural Type

