

# North Lake School

North Lake SD 14

Lake\_sch03A

Building Type School	County Lake	
Street 57566 Fort Rock Rd		
City Silver Lake	State OR	Zip 97638
Latitude 43.245	Longitude 120.90262	
Tracking Code RVS in 2006	Inspection Date 6/27/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	1.6	-0.8	0	0	5.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Lake School

## Final RVS Score

Final Type	Final Score
W2	5.1

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# North Lake School

Lake\_sch03A

Enrollment 208	Year Built (Field Verified) 1991	Year Built (Alt. Source) 1991	Est. Decade Built 1990
Total Area (square ft) 54000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped Reentrant Corners: L Shaped (Adjacent Build/Entity) None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 SW General Site		 S Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Lake School

North Lake SD 14

## Lake\_sch03B

Building Type	County	
School	Lake	
Street		
57566 Fort Rock Rd		
City	State	Zip
Silver Lake	OR	97638
Latitude	Longitude	
43.24524	120.90289	
Tracking Code	Inspection Date	
RVS in 2006	6/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card


## North Lake School

## Final RVS Score

Final Type      Final Score

## FEMA-154 Collapse Potential

Low (<1%)



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Lake School

Lake\_sch03B

Enrollment 208	Year Built (Field Verified) 1991	Year Built (Alt. Source) 1991	Est. Decade Built 1990
Total Area (square ft) 54000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



W Primary Structural Type



N General Site



N Primary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Lake School

North Lake SD 14

Lake\_sch03C

Building Type School	County Lake	
Street 57566 Fort Rock Rd		
City Silver Lake	State OR	Zip 97638
Latitude 43.24533	Longitude 120.90197	
Tracking Code RVS in 2006	Inspection Date 6/27/2006	



Seismicity Zone: Moderate										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	1.6	-0.8	0	0	5.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Lake School

**Final RVS Score**

Final Type W2	Final Score 5.6
------------------	--------------------

**FEMA-154 Collapse Potential**

Low (<1%)
-----------



# North Lake School

Lake\_sch03C

Enrollment 208	Year Built (Field Verified) 1991	Year Built (Alt. Source) 1991	Est. Decade Built 1990
Total Area (square ft) 54000	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Primary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries