

Lane CC

| | | |
|------------------------------------|-----------------------------|--------------|
| Building Type Community_College | County Lane | |
| Street 1275 S River Road | | |
| City Cottage Grove | State OR | Zip 97424 |
| Latitude 43.78788 | Longitude 123.07037 | |
| Tracking Code New Building | Inspection Date 3/1/2007 | |

Seismicity Zone: High

| FEMA 154 Rapid Visual Screening Score Card | | | | | | | | | | |
|--|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Branch - Cottage Grove Center

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| | |

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



Oregon Geology

Branch - Cottage Grove Center

Lane_coc22A

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| 18613 | 1996 | 1996 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| | | | |
| | | | |
| | | | |
| Falling Hazards | | Poor Conditions | |
| | | | |
| | | | |
| | | | |