

Lane County Fire District 1

Lane Co Fire Dist #1

Lane_fir03A

| | | |
|---------------------------------|------------------------------|--------------|
| Building Type Fire - RFPD | County Lane | |
| Street 88050 Territorial Hwy | | |
| City Veneta | State OR | Zip 97487 |
| Latitude 44.04762 | Longitude 123.35229 | |
| Tracking Code RVS in 2006 | Inspection Date 7/24/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | RM1 | 2.8 | -1 | -0.5 | 0 | 0 | 0 | -0.6 | 0 | 0.7 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Lane County Fire District 1

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1 | 0.7 |

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Lane County Fire District 1

Lane_fir03A

| | | | |
|---|-----------------------------|--|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1990 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 2 | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: Other | | Steps in Elevation View: Single Change | |
| None | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | | | |
| W Vertical Irregularity Primary Large openings in the back of the building, so no torsion. | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries