

Pleasant Hill RFPD

Pleasant Hill RFPD

Lane_fir04A

Building Type Fire - RFPD	County Lane	
Street 36024 Highway 58		
City Pleasant Hill	State OR	Zip 97455
Latitude 43.96604	Longitude 122.93111	
Tracking Code RVS in 2006	Inspection Date 7/20/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary	S3	3.8	0	-0.5	0	0	0	-1	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Pleasant Hill RFPD

Final RVS Score

Final Type	Final Score
W2	0.1


FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE	Vertical Irregularity Primary	NW	Plan Irregularity Primary
		S Vertical Irregularity Primary	
		S Vertical Irregularity Primary	

