

Lane Rural Fire Rescue

Lane Rural Fire Rescue

Lane_fir17A

Building Type Fire - RFPD	County Lane	
Street 91970 Territorial Rd		
City Eugene	State OR	Zip 97402
Latitude 44.15638	Longitude 123.30804	
Tracking Code RVS in 2006	Inspection Date 7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	0	0	0	0	0	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lane Rural Fire Rescue

Final RVS Score

Final Type	Final Score
W1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lane Rural Fire Rescue

Lane_fir17A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N Vertical Irregularity Primary Irregularity is due to hose tower		NE Plan Irregularity Secondary Large opening in the front of the building indicates possible torsion problem	
			
		E Plan Irregularity Primary out of plane lateral system	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries