

# Lowell RFPD

Lowell RFPD

Lane\_fir21A

Building Type Fire - RFPD	County Lane	
Street 389 North Pioneer St		
City Lowell	State OR	Zip 97452
Latitude 43.92263	Longitude 122.78157	
Tracking Code RVS in 2006	Inspection Date 7/20/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	-0.6	0	0	2.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lowell RFPD

## Final RVS Score

Final Type	Final Score
S3	2.7

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Plan Irregularity Primary	NE Vertical Irregularity Primary and also torsion -eccentric stiffness	NE Other Transition between 1975 construction and new 2003 construction. They were made to look identical.	

