

Pleasant Hill RFPD Station #2

Lane_fir40A

Pleasant Hill RFPD

Building Type		County	
Fire - RFPD		Lane	
Street			
36751 Jasper Lowell Rd			
City	State	Zip	
Jasper	OR	97438	
Latitude		Longitude	
43.99797		122.9042	
Tracking Code		Inspection Date	
RVS in 2006		7/20/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	-0.5	0	1.6	-0.2	0	0	6.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pleasant Hill RFPD Station #2

Final RVS Score

Final Type

Final Score

W1

6.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pleasant Hill RFPD Station #2

Lane_fir40A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W General Site