

Siuslaw Valley F & R - Station 2

Lane_fir54A

Siuslaw Valley F & R

Building Type	County	
Fire - RFPD	Lane	
Street		
243 Laurel St		
City	State	Zip
Florence	OR	97439
Latitude	Longitude	
43.96781	124.10703	
Tracking Code	Inspection Date	
RVS in 2006	8/4/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Siuslaw Valley F & R - Station 2

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



Siuslaw Valley F & R - Station 2

Lane_fir54A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		Building On Hill or Sloped Site	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Primary Structural Type		NE Plan Irregularity Primary	
		NW Vertical Irregularity Primary sloped site (minor). Reentrant corner also.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries