

# Mohawk Valley RFD

Lane\_fir65A

Mohawk Valley RFD

Building Type		County	
Fire - RFPD		Lane	
Street			
92068 Marcola Rd			
City	State	Zip	
Springfield	OR	97478	
Latitude	Longitude		
44.17079	122.87087		
Tracking Code	Inspection Date		
RVS in 2006	7/20/2006		



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	1.6	-0.8	0	0	2.1
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Mohawk Valley RFD

## Final RVS Score

Final Type

Final Score

RM1

0.3

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Building On Hill or Sloped Site
Torsion: Eccentric Stiffness	Steps in Elevation View: 2 to 3 Changes
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Other



S Elevation View



S Plan Irregularity Secondary



NE Vertical Irregularity Primary



S Primary Structural Type and secondary type also