

# Santa Clara RFPD

Santa Clara RFPD

Lane\_fir69A

Building Type Fire - RFPD	County Lane	
Street 3939 River Rd		
City Eugene	State OR	Zip 97404
Latitude 44.12232	Longitude 123.13948	
Tracking Code RVS in 2006	Inspection Date 7/20/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	W2	3.8	-2	-0.5	0	2.4	0	0	0	3.7
Tertiary		0	0	0	0	0	0	0	0	0

Santa Clara RFPD

## Final RVS Score

Final Type	Final Score
RM1	1.3

## FEMA-154 Collapse Potential

Moderate (>1%)



Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
NE	Plan Irregularity Primary	E	General Site
S	General Site	NE	Vertical Irregularity Primary

