

Siuslaw Valley F & R - Station 8

Lane_fir72A

Siuslaw Valley F & R

Building Type Fire - RFPD	County Lane	
Street 83381 Clear Lake Rd		
City Florence	State OR	Zip 97439
Latitude 43.89808	Longitude 124.10157	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

Siuslaw Valley F & R - Station 8

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Siuslaw Valley F & R - Station 8

Lane_fir72A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Steps in Elevation View: Single Change	
None		Building On Hill or Sloped Site	
None		Internal Discontinuous Diaphram (large internal opening)	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S Vertical Irregularity Secondary sloped site		E Plan Irregularity Primary Back wall is solid indicating a potential torsion problem.	
		E Primary Structural Type RM1	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries