

# Springfield Police Dept

City of Springfield

Lane\_pol01A

Building Type	County
EOC-Public Safety Answering P	Lane
Street	
344 A St	
City	State Zip
Springfield	OR 97477
Latitude	Longitude
44.04731	123.02145
Tracking Code	Inspection Date
RVS in 2006	7/26/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	0	0	0	2.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Springfield Police Dept

## Final RVS Score

Final Type	Final Score
PC1	2.1

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Springfield Police Dept

Lane\_pol01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	General Site	W	Primary Structural Type
			
SW	Plan Irregularity Primary	SW	Vertical Irregularity Primary
			
SE	Vertical Irregularity Primary	SW	Vertical Irregularity Primary
			
N	Vertical Irregularity Primary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries