

# Eugene Police Dept

City of Eugene

Lane\_pol02A

Building Type Police - City	County Lane	
Street 777 Pearl St		
City Eugene	State OR	Zip 97401
Latitude 44.05186	Longitude 123.08889	
Tracking Code RVS in 2006	Inspection Date 8/1/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	C1	2.5	-1.5	-0.5	0	0	0	0	0	0.5
Tertiary	RM2	2.8	-1	-0.5	0	0	0	0	0	1.3

Eugene Police Dept

## Final RVS Score

Final Type	Final Score
C1	0.5

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Soft Story	
None		Short Columns	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Primary Structural Type	E	Vertical Irregularity Secondary short columns
			
S Primary Structural Type		E Vertical Irregularity Secondary short columns	
			
N	Other	E	General Site
police vechles are parked under the building.			
		Oregon Geology	
Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment Oregon Department of Geology and Mineral Industries			