

# Creswell Sheriff's Office

Lane County

Lane\_pol04A

Building Type	County	
Police	Lane	
Street		
13 S 1st St		
City	State	Zip
Creswell	OR	97426
Latitude	Longitude	
43.91757	123.02018	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

Creswell Sheriff's Office

## Final RVS Score

Final Type	Final Score
RM1	0.7

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1952	1952	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N	General Site	NE Vertical Irregularity Primary vertical irregularity is due to the fire station on the left side of the picture. Lane_pol04 is in the city hall building on the right side of the pic	

