

# Eugene Police Station 1 - Monroe St Station

City of Eugene

Lane\_pol13A

Building Type Police - City	County Lane	
Street 788 Monroe St		
City Eugene	State OR	Zip 97404
Latitude 44.05303	Longitude 123.10463	
Tracking Code RVS in 2006	Inspection Date 8/18/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	0	0	0	-0.4	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Eugene Police Station 1 - Monroe St Station

## Final RVS Score

Final Type	Final Score
RM1	1.4

## FEMA-154 Collapse Potential

Moderate (>1%)



# Eugene Police Station 1 - Monroe St Station

Lane\_pol13A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Primary Structural Type		NW Plan Irregularity Primary reentrant corner	
		W Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries