

# Spencer Butte Middle School

Eugene SD 4J

Lane\_sch20A

Building Type	County	
School	Lane	
Street		
500 E 43rd Ave		
City	State	Zip
Eugene	OR	97405
Latitude	Longitude	
44.00762	123.08515	
Tracking Code	Inspection Date	
Structural Engineering Report	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	0	0	0	2.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Spencer Butte Middle School

## Final RVS Score

Final Type

Final Score

PC1

2.1

FEMA-154 Collapse Potential

Low (<1%)

# No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
447		1960	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
82414	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions