


Briggs Middle School

Springfield SD 19

Lane_sch28A

Building Type		County	
School		Lane	
Street			
2355 Yolanda Ave			
City		State	Zip
Springfield		OR	97477
Latitude		Longitude	
44.07158		122.99059	
Tracking Code		Inspection Date	
Previous FEMA-154 Report		9/15/2006	



Seismicity Zone: High										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Briggs Middle School	
Final RVS Score	
Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential
Low (<1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
553		1963	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
93303	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions