

Maple Elementary School

Springfield SD 19

Lane_sch34A

| | | | |
|--------------------------|--|-----------------|-------|
| Building Type | | County | |
| School | | Lane | |
| Street | | | |
| 2109 J St | | | |
| City | | State | Zip |
| Springfield | | OR | 97477 |
| Latitude | | Longitude | |
| 44.05481 | | 122.99382 | |
| Tracking Code | | Inspection Date | |
| Previous FEMA-154 Report | | 9/15/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3.8 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Maple Elementary School

Final RVS Score

Final Type

Final Score

W2

3.8

FEMA-154 Collapse Potential

Low (<1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| 327 | | 1947 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 41706 | 1 | No | No |

| | |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| | |
| | |
| | |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| | |
| | |
| | |



S General Site