


# Yolanda Elementary School

Springfield SD 19

Lane\_sch41A

Building Type		County	
School		Lane	
Street			
2350 Yolanda Ave			
City		State	Zip
Springfield		OR	97477
Latitude		Longitude	
44.07316		122.99043	
Tracking Code		Inspection Date	
Previous FEMA-154 Report		9/15/2006	



Seismicity Zone: High											Yolanda Elementary School	
FEMA 154 Rapid Visual Screening Score Card											Final RVS Score	
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score	Final Type	Final Score
Primary	W2	3.8	0	0	0	0	0	0	0	3.8	W2	3.8
Secondary		0	0	0	0	0	0	0	0	0		
Tertiary		0	0	0	0	0	0	0	0	0		
											FEMA-154 Collapse Potential	
											Low (<1%)	

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
426		1963	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
45121	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions