

Veneta Elementary School

Lane_sch46B

Fern Ridge SD 28J

Building Type		County	
School		Lane	
Street			
88131 Territorial Hwy			
City	State	Zip	
Veneta	OR	97487	
Latitude		Longitude	
44.0499		123.34997	
Tracking Code		Inspection Date	
RVS in 2006		7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	2.4	0	-0.8	0	4.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Veneta Elementary School

Final RVS Score

Final Type

Final Score

W2

4.9

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
303		1945	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
44283	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:T shaped (Adjacent Build/Entity)	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Plan Irregularity Primary shows building B on the left and building A on the right.



Veneta Elementary School

Lane_sch46A

Fern Ridge SD 28J

Building Type		County	
School		Lane	
Street			
88131 Territorial Hwy			
City	State	Zip	
Veneta	OR	97487	
Latitude		Longitude	
44.04987		123.35048	
Tracking Code		Inspection Date	
RVS in 2006		7/24/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Veneta Elementary School

Final RVS Score

Final Type

Final Score

RM1

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
303		1945	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
44283	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: T shaped (Adjacent Build/Entity	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Other
covered playground attached to the gym



SE Plan Irregularity Primary



W Plan Irregularity Secondary
shows building B on the right and building A on the left



NE General Site



SW Plan Irregularity Primary