

Creswell High School

Creswell SD 40

Lane_sch49A

Building Type School	County Lane	
Street 33390 E Nieblock Ln		
City Creswell	State OR	Zip 97426
Latitude 43.92462	Longitude 123.02844	
Tracking Code RVS in 2006	Inspection Date 11/17/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Creswell High School

Final RVS Score

Final Type	Final Score
W1	1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Creswell High School

Lane_sch49A

Enrollment 354	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 103098	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other Reentrant Corners: Other (Adjacent Build/Entity) None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Vertical Irregularity Primary		W Field Verified Year Built	
			
N Elevation View		S Elevation View	
			
		SE Plan Irregularity Primary	

Creswell High School

Creswell SD 40

Lane_sch49B

Building Type School	County Lane	
Street 33390 E Nieblock Ln		
City Creswell	State OR	Zip 97426
Latitude 43.92431	Longitude 123.02839	
Tracking Code RVS in 2006	Inspection Date 11/17/2006	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	0	-0.6	0	1.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Creswell High School

Final RVS Score

Final Type PC1	Final Score 1.5
-------------------	--------------------

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Creswell High School

Lane_sch49B

Enrollment 354	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1990	Est. Decade Built 1990		
Total Area (square ft) 103098	Number of Stories 2	Basement	Pounding Potential No		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: Other		Steps in Elevation View: Single Change			
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes			
None		None			
Falling Hazards		Poor Conditions			
None		None			
None		None			
None		None			
	W Primary Structural Type		SE Plan Irregularity Primary		E Vertical Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Creswell High School

Creswell SD 40

Lane_sch49C

Building Type School	County Lane	
Street 33390 E Nieblock Ln		
City Creswell	State OR	Zip 97426
Latitude 43.92417	Longitude 123.02903	
Tracking Code RVS in 2006	Inspection Date 11/17/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Creswell High School

Final RVS Score

Final Type	Final Score
W1	1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Creswell High School

Lane_sch49C

Enrollment 354	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 103098	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 S Plan Irregularity Primary			

Creswell High School

Creswell SD 40

Lane_sch49D

Building Type School	County Lane	
Street 33390 E Nieblock Ln		
City Creswell	State OR	Zip 97426
Latitude 43.92471	Longitude 123.02943	
Tracking Code RVS in 2006	Inspection Date 11/17/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	2.4	0	-0.8	0	4.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Creswell High School

Final RVS Score

Final Type	Final Score
W2	4.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Creswell High School

Lane_sch49D

Enrollment 354	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1990
Total Area (square ft) 103098	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		None	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Plan Irregularity Primary		NE Plan Irregularity Primary	