

Harrison Elementary School

South Lane SD 45J3

Lane_sch51A

Building Type	County
School	Lane
Street	
1000 S 10th	
City	State Zip
Cottage Grove	OR 97424
Latitude	Longitude
43.79037	123.05847
Tracking Code	Inspection Date
RVS in 2006	7/20/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Tertiary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3

Harrison Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Harrison Elementary School

Lane_sch51A

Enrollment 352	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1948	Est. Decade Built 1950
Total Area (square ft) 39348	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
			
W General Site		W Primary Structural Type also shows secondary structure type	
		W Plan Irregularity Primary also shows a URM chimney	
			
NW Vertical Irregularity Primary also shows S3 for the upper level.		S Other shows a covered playground next to the school.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
 Oregon Department of Geology and Mineral Industries