

# Lincoln Middle School

South Lane SD 45J3

Lane\_sch52A

Building Type		County	
School		Lane	
Street			
1565 S 4th st			
City		State	Zip
Cottage Grove		OR	97424
Latitude		Longitude	
43.78379		123.06551	
Tracking Code		Inspection Date	
RVS in 2006		7/20/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

Lincoln Middle School

## Final RVS Score

Final Type

Final Score

RM1

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
560		1963	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
91698	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
Other: General	None
None	None
None	None



E Primary Structural Type



E General Site



N General Site

W Falling Hazard  
rafter toe-nailed to ledgerE Vertical Irregularity Primary  
reentrant corner