

# Irving Elementary School

Bethel SD 52

Lane\_sch58A

Building Type		County	
School		Lane	
Street			
3200 Hyacinth St.			
City	State	Zip	
Eugene	OR	97404	
Latitude		Longitude	
44.1107		123.1523	
Tracking Code		Inspection Date	
SER & RVS2006		7/20/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Irving Elementary School

## Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
444		1965	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
8350	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
Non-Parallel System	None
Out of Plane Lateral-Force-Resistance Elements	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW General Site



NE General Site



NE Plan Irregularity Secondary

