

Westridge Middle School

Oakridge SD 76

Lane_sch66A

Building Type	County	
School	Lane	
Street		
46433 Westfir Rd.		
City	State	Zip
Westfir	OR	97492
Latitude	Longitude	
43.75902	122.52894	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary	S3	3.8	0	-0.5	0	0	-0.6	0	0	2.7

Westridge Middle School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Westridge Middle School

Lane_sch66A

Enrollment 157	Year Built (Field Verified) 1954	Year Built (Alt. Source) 1954	Est. Decade Built 1960
Total Area (square ft) 45524	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
			
W Vertical Irregularity Primary reentrant corner		W Primary Structural Type	N General Site
			
SE Plan Irregularity Primary		SE General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries