

# Marcola Elementary School

Marcola SD 79J

Lane\_sch94A

Building Type School	County Lane	
Street 92550 School House Rd.		
City Marcola	State OR	Zip 97454
Latitude 44.17416	Longitude 122.86296	
Tracking Code RVS in 2006	Inspection Date 7/20/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Marcola Elementary School

## Final RVS Score

Final Type	Final Score
W2	0.5

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Marcola Elementary School

Lane\_sch94A

Enrollment 161	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 29421	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



S General Site



W Vertical Irregularity Primary



NE Vertical Irregularity Primary and reentrant corner



NE General Site



E General Site